

Gavin Butler

From: Trish Chaney <Trish.Chaney@northernbeaches.nsw.gov.au>
Sent: Monday, 23 August 2021 12:07 PM
To: Gavin Butler
Cc: Wendy Dunnet
Subject: RE: Newport Matters

Hello Gavin

I hope you and your families are all staying well during this lockdown.

Thank you for your email. I've sent the pics of the hole in the soft play surface to Jeremy to arrange repairs.

In regards to the Melaleuca Street steps, it is Council's preference to build the steps close to the boundary and so we need to wait for the fence encroachment to be resolved before we undertake a survey of the area then move to concept design. I have made sure that they are aware of the NRA's concerns about this project being delayed.

Kind regards

Trish Chaney
Community Liaison Coordinator

CEO
t 02 8495 6181 m 0466 625 214
trish.chaney@northernbeaches.nsw.gov.au
northernbeaches.nsw.gov.au



From: Gavin Butler <gebutler@aapt.net.au>
Sent: Thursday, 19 August 2021 4:39 PM
To: Trish Chaney <Trish.Chaney@northernbeaches.nsw.gov.au>
Cc: Wendy Dunnet <wendydunnet@gmail.com>
Subject: Newport Matters

Trish,

Firstly I want to thank you for following up on the handball drain matter at the Newport Youth Space. I attach a photo of the fix and I have checked it against the size of a handball – perfect result thank you. Secondly I have also added a second photo of a hole that has appeared in the surface underneath the exercise area – if that could be sent on to someone to fix before it gets larger (unless it was fixed in the last couple of days since I have been there and if so thank you).

On another matter re the link between Bungan Head Rd and Melaleuca Street I note in your reply to Wendy of the 5th August that the steps installation has been moved back a year. This was on the current year's budget (copy attached) so if that is the case we are very disappointed as it really needs doing before there is an accident. I know that there is a land encroachment issue that was mentioned at the time we met on site last year and in your note however I can't see how that land encroachment would affect where the steps would go. If you could recheck this we would be grateful.